M10

M9

M8

M7

M6

M5

M4

M3

M2

M1

G10

G9

G8

G7

G6

G5

G4

G3

G2

G1

M1-M3 is negative, M4-M10 is positive;

G1-G3 is negative, G4-G10 is positive;

Note: The chromaticity bar can only be used as the chromaticity guide and it should be used in conjunction with IFU.